ILLINOIS ENVIRONMENTAL PROTECTION AGENCY MEMORANDUM

DATE: 5 January 2011

TO: Bureau of Land File

FROM: Michelle Cozadd, BOL/FOS Collinsville Region

SUBJECT: LPC #1198010003 – Madison County

Hartford/Chemetco

FOS File

On December 15, 2010, a site visit was conducted at Chemetco, Inc. I met with Jorge Garcia, ES&H Manager for the Estate of Chemetco and Mr. Michael Murray, Supervisor for AIS.

Receiving Building

The material that was taken from the Foundry to the Fines Building was placed in four cardboard boxes. The boxes were being moved to the Receiving Building during the site visit. One box in the Receiving Building is shown in the attached photos #001, #002, and #003. The second box on the forklift outside of the Receiving Building is shown in attached photo #004. The remaining two boxes in the Fines Building are shown in the attached photo #007. These boxes will be relocated to the Receiving Building by the end of the day.

Fines Building

The door on the Fines Building is shown in the attached photo #005. The attached photo #006 shows the segregated broken concrete, damaged dimensional lumber, and other miscellaneous wastes from screening operations in the Fines Building. This pile is in the process of being shipped off-site as a hazardous waste for cadmium (D006) and lead (D008).

Dome Building

Two super sacs of spent sand from decontamination procedures was staged for removal in the Dome Building (see attached photo #008). Piles of scrap metal to be decontaminated are shown in the attached photos #008, #009, and #010.

Foundry

The attached photo #011 is the interior of the foundry as seen from the north doorway. The pile of silica sand shown in the attached photo #012 was moved to the Foundry about one and half weeks ago.


AAF Area

AIS is continuing demolition in the AAF area (see attached photos #013 through #016). The attached photo #017 is an overview of the site as seen from a nearby roadway.

cc: Regional Filecc: Erin Rednour

cc: Michelle Kerr – US EPA

LPC #1198010003 – Madison County Hartford/Chemetco FOS File



December 15, 2010 Inspection
Direction of Photo →
Photo Locations Approximate
Not to Scale



Date: 15 December 2010

Time: 8:44 am Direction: W

Photo by: M. Cozadd Exposure #: 001 Comments: One of four cardboard boxes of material from Foundry that was taken to Fines Building and is currently in Receiving Building.



Date: 15 December 2010

Time: 8:44 am Direction: W

Photo by: M. Cozadd Exposure #: 002 Comments: One of four cardboard boxes of material from Foundry that was taken to Fines Building and is currently in Receiving Building.





Date: 15 December 2010

Time: 8:45 am Direction: W

Photo by: M. Cozadd Exposure #: 003 Comments: Material in Receiving Building.



Date: 15 December 2010

Time: 8:45 am Direction: N

Photo by: M. Cozadd Exposure #: 004 Comments: Second of four cardboard boxes of material from Foundry that was taken to Fines Building and is currently being taken by forklift to the Receiving Building.



Date: 15 December 2010

Time: 8:49 am Direction: N

Photo by: M. Cozadd Exposure #: 005 Comments: Door on Fines Building.



Date: 15 December 2010

Time: 8:49 am Direction: NW

Photo by: M. Cozadd Exposure #: 006

Comments: Segregated

broken concrete, damaged dimensional lumber, and other miscellaneous wastes from screening operations in Fines

Building.



Date: 15 December 2010

Time: 8:50 am Direction: N

Photo by: M. Cozadd Exposure #: 007 Comments: Last two of four cardboard boxes of material from Foundry that was taken to Fines Building. Material to be

relocated to the Receiving Building.



Date: 15 December 2010

Time: 8:55 am Direction: E

Photo by: M. Cozadd Exposure #: 008 Comments: Two super sacs of spent sand from decontamination procedures staged in Dome Building for removal off-site.



Date: 15 December 2010

Time: 8:57 am Direction: E

Photo by: M. Cozadd Exposure #: 009

Comments: Scrap metal

staged inside Dome Building for

Building for decontamination.



Date: 15 December 2010

Time: 8:57 am Direction: SE

Photo by: M. Cozadd Exposure #: 010 Comments: Scrap metal staged inside Dome Building for decontamination.



Date: 15 December 2010

Time: 8:59 am Direction: S

Photo by: M. Cozadd Exposure #: 011 Comments: Interior of Foundry as seen from

north doorway.



Date: 15 December 2010

Time: 8:59 am Direction: SW

seen from north

Photo by: M. Cozadd Exposure #: 012 Comments: Pile of silica sand in Foundry as

doorway.



Date: 15 December 2010 **Time:** 9:02 am **Direction:** SW

Photo by: M. Cozadd Exposure #: 013 Comments: Demolition

in AAF area.



Date: 15 December 2010

Time: 9:03 am Direction: W

Photo by: M. Cozadd Exposure #: 014 Comments: Demolition

in AAF area.





Date: 15 December 2010 Time: 9:03 am Direction: NW Photo by: M. Cozadd

Exposure #: 015
Comments: Demolition

in AAF area.



Date: 15 December 2010

Time: 9:04 am Direction: E

Photo by: M. Cozadd Exposure #: 016 Comments: Scrap metal staged near Tank Building from demolition

in AAF area.



Date: 15 December 2010

Time: 9:26 am Direction: W

Photo by: M. Cozadd Exposure #: 017

Comments: Overview of

site.

NO PHOTO